



Sanitary Sewer Overflow Annual Report

Division of Surface Water

Date: 1/26/2015
Facility name: City of Wooster WRF
Ohio NPDES permit no.: 3PD00013
Period covered by report: 1/1/2014/12/31/2014

Contact person

Name: Kevin P Givins
Title: Utilities Manager
Mailing address: 1020 Old Columbus Road
Wooster, OH 44691
Telephone: (330)263 - 5285
Email: kgivins@woosteroh.com

Certification:

I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.

Name Kevin P Givins
(typed):

Title: Utilities Manager

Signature:

Date:

1-26-2015

Enter narrative analysis of WIB patterns by location, frequency and cause.

Of the 22 reported instances of water in basement (WIB), 13 were due to customer lateral blockage caused by debris and grease in residential sewer laterallines. Lateral blockages were registered in all sewersheds except for the Killbuck South area. Residents removed the blockages themselves or hired contractors to remove the obstructions. No repeat incidents have been reported.

The Little Apple Creek Sewershed experienced two WIB incidents caused by debris and roots in the collection system. City personnel were dispatched to remove the blockage and the area was added to the annual root treatment list. The City annually hires a contractor to provide root treatment in areas known to have excessive root invasion of the collection system mains.

The Christmas Run Sewershed saw three WIB incidents in 2014. An equipment failure at a sewer pump station was determined to cause one of the incidents. Repairs were made to the pump station and no repeat incidents have occurred. Root blockage on Monterey Street caused a WIB event. The blockage was removed and the area is now on the root treatment list. Debris was found in the main on Impala Street causing the third WIB incident. The debris was removed and no additional occurrences have been reported.

The Bever Sewershed had one reported WIB event in 2014. Debris in the main was found and removed by the City Collection Team.

The Killbuck South Sewershed had one reported WIB incident caused by excessive roots in the main. City personnel removed the blockage and the area has been added to the annual root treatment list.