

**SANITARY SEWER OVERFLOW
ANNUAL REPORT**

DATE: 02/01/11

FACILITY NAME: City of Wooster

OHIO NPDES PERMIT NO: 3PD000013

PERIOD COVERED BY REPORT: 1/1/10-12/31/10

CONTACT PERSON

NAME: James L. Borton

TITLE: Utilities Manager

MAILING ADDRESS:

1020 Old Columbus Rd.
Wooster, Ohio 44691

TELEPHONE: (330) 263-5293

EMAIL: jborton@woosteroh.com

I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION IN THIS REPORT AND ALL ATTACHMENTS. BASED ON MY INQUIRY OF THOSE PERSONS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION CONTAINED IN THE REPORT, I BELIEVE THAT THE INFORMATION IS TRUE, ACCURATE, AND COMPLETE.



Signature of Official



Date

Utilities Manager

Title

Enter narrative analysis of WIB patterns by location, frequency and cause.

925 Green Valley Lane and 960 Curtwood (houses are back to back on same sewer line at lowest elevation prior to entering 90 degree turn manhole) within the Killbuck South sewershed had simultaneous WIB events on 6/5/10 lasting 0.5 hours. The week and hours leading up to the event experienced significant wet weather patterns leading to saturated ground and flooding conditions in parts of town. Specifically, the immediate 24 hours prior to the event saw a total of 3" of precipitation. The WIB appeared to be driven by excessive I&I due to the rain events as the water subsided within minutes of the rainstorm leaving the area. The problem has not reoccurred to date; however, the entire Killbuck South sewershed is scheduled for smoke testing in 2011 to identify potential I&I sources.

2598 Jane St. within the Killbuck South sewershed experienced WIB on 8/13/10 for one hour due to root intrusion. The roots were removed and the area added to the City's on-going root treatment program. There has not been a reoccurrence of the WIB.