



Sanitary Sewer Overflow Annual Report

Division of Surface Water

Date: 1/23/2016
Facility name: City of Wooster WRRF
Ohio NPDES permit no.: 3PD00013
Period covered by report: 1/1/2016-12/31/2016


Contact person

Name: Kevin P Givins
Title: Utilities Manager
Mailing address: 1020 Old Columbus Road
Telephone: (330)263 - 5285
Email: kgivins@woosteroh.com

Certification:

I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.

Name Kevin P Givins **Title:** Utilities Manager
(typed):

Signature:  **Date:** 1-25-2017

Enter narrative analysis of WIB patterns by location, frequency and cause.

The Little Apple Creekk Sewershed experienced the most "water in Basement" (WIB) events in 2016. There were 5 reported instances of WIB throughout the year in the sewershed. One was caused by equipment failure at a sewer lift station, one by a main blockage and the rest were blockages in the owner's lateral line. The remaining 6 reported WIB events in the other sewersheds were all caused by owner lateral blockagedue to roots and other debris.

The City of Wooster maintains an annual root treatment programto mitigate obstructions by root intrusion. Targeted areas are treated to reduceroot blockage in conjunction with regular jetting of known problem mains in the collection system to clear grease, roots and debris.