



# Sanitary Sewer Overflow Annual Report

Division of Surface Water

**Date:** 2/23/23  
**Facility name:** City of Wooster Water Recovery Facility  
**Ohio NPDES permit no.:** 3PD00013\*RD  
**Period covered by report:** 2022

**Contact person**

**Name:** Chad Frank  
**Title:** Master Operator  
**Mailing address:** 1123 Old Columbus Road, Wooster Ohio 44691  
**Telephone:** (330)263 - 5294  
**Email:** cfrank@woosteroh.com

**Certification:**

*I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.*

**Name** Chad Frank **Title:** Master Operator

**(typed):** \_\_\_\_\_

**Signature:** \_\_\_\_\_

**Date:** 2-23-23







Enter narrative analysis of WIB patterns by location, frequency and cause.

Little Apple Creek had an instance caused by a homeowners lateral and another due to roots causing a blockage in the main line. Christmas Run had two instances which were both caused by the homeowners laterals.