



# Sanitary Sewer Overflow Annual Report

Division of Surface Water

**Date:** 1/16/20  
**Facility name:** City of Wooster Water Resource Recovery Facility  
**Ohio NPDES permit no.:** 3PD00013\*RD  
**Period covered by report:** 1/1/2019 - 12/31/2019

**Contact person**

**Name:** Steven S. Carathers  
**Title:** Supervisor  
**Mailing address:** 1123 Old Columbus Rd. Wooster, Ohio 44691  
**Telephone:** (330)263 - 5294  
**Email:** scarathers@woosteroh.com

**Certification:**

*I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.*

**Name** Steven S. Carathers **Title:** Supervisor  
**(typed):** \_\_\_\_\_

**Signature:**  \_\_\_\_\_ **Date:** 1-16-2020







Enter narrative analysis of WIB patterns by location, frequency and cause.

Elm Street Sewershed had the most water in basements (WIB) with 6 reported due to various issues. There were 3 to the Little Applecreek sewershed due to roots, debris and other blockages and 2 in the Killbuck South sewershed due extreme weather. Wooster continues to use a root treatment system along with regular jetting of known problem areas. Wooster has also started a relining project in hopes of reducing I&I and the effects of roots.